

Constraint : HLR_MODG_0100 in AnActor

General Properties

Name:

Stereotype:

Defined in:

Body

Description

Title: Reset behavior
 Content: The application software shall perform a reset of the partition in less than 300 ms except in case of MACSII limitation.
 Category: Functional
 Upward Req: MB_BCS_IMA_20, MB_BCS_IMA_37, MB_SCS_IMA_37.

Locate OK Apply

FIG.1




FIG.2




FIG.3




FIG.4